

Date	RSID	Surveyor	Description	InstNo
12/31/1875	000056	Henly, H	Legal survey in Sections 23, 24, 25 & 26 -T7N-R1W (All index corners fall in lake)	
9/1/1882	000057	Buskirk, M.	Legal survey in Section 26-T7N-R1W No monument types or distances	
9/11/1882	001003	Buskirk, M.	Legal survey in Section 25. All corners fall in lake.	
10/10/1882	000055	Buskirk, M.	Legal survey in Sections 25 and 26 - T7N-R1W. Monuments not described, both section corners referenced fall in the lake	
3/3/1883	001335	Buskirk, M.	Legal survey	
9/7/1894	001001	Buskirk, M.	Legal survey in Section 24. All corners except for Y13 fall in the lake.	

